

TRI-VALLEY CHEVY CLUB TECH. TIP LIBRARY

DEC. 1974 THRU Dec. 2006

AIR CONDITIONING

Add-on A/C-installation	Apr. 84
Add-on A/C compressor (57)	Jul.87
Add-on A/C (57 in-dash) install	May 89/Mar.89
In-dash A/C 1955-56	May 90
In-dash A/C 6-cyl.	June 90
"Getting aired" air conditioning	Feb.83
HFC-134a Air Conditioning Installation	July 95
55-56 big block HFC-134a in dash A/C	Aug. 96
55-57 in dash A/C installation	July 03
5-7 vintage A/C & cross flow rad. install	July 05
5-7 factory A/C vent install	July 06

ALARMS

Burglar alarm installation	Feb. 80
----------------------------	---------

ANTENNA

Rear(single or dual) installation	Mar. 90
Original (1957 front & rear)-installation	Mar. 77
Replacement-installation	Feb. 82

BATTERY

Original-tartops researched	Nov. 84
Taking care of your tar top battery	Nov. 92

BEARINGS

Original (front) installation	May 81
Original (rear) installation	May 83
Replacement (front) ball to roller conversion	Feb.83
Tapered roller bearings	Jan.79
Tapered bearing hub conversion	Dec. 02

BODY

Panels / body repair	Dec.76
Body openings-(55) tolerances & specs.	Aug.80
Door shimming & adjustments	Jul.77
Fender (front)-panel replacement	Apr.80
Fender (front) rust repair	May 93
Floor pan-panel replace	Aug 78 sept.89 Oct 89
Hood to cowl screen (55-56)	Nov.92
Inner/ outer rocker installation	Nov.90
Quarter-full panel(57)-installation	Jan.86
Sedan quarter panel installation	Sep.94
Sheet-metal "where do I start?"	Dec.90
Roof pillar (nomad)-repair & leading	Aug.77
Tail pan installation	Oct.90
Hood lock for your classic	Apr.81
Door repair and reskinning	March 96
Front End Seal Location	Dec. 96
Rear area sheet metal identification	Dec.97
Floorpan & brace area sheetmetal I.D.	Jan. 99
55 side stainless installation	May 02
Inside hood latch release kit install	Nov. 03
55-57 body mounts & shim install	Jan.04
55-57 Sheet metal installation	Jan. 04
5-7 front end sheet metal & seal install	Jan. 04
57 rear fin crown moulding installation	March 04
5-7 wagon tailgate hinge rebuild	June 05
5-7 elec. deck lid release kit	June 05
5-7 body mount install & shim	Oct. 05
Fiberglass inner fender installation	Jan.07
Wagon liftgate gas struts install	April 07

BRAKES

Disc brake bolt-on conversion	Jun.82/Aug.82
Dual master cylinder-installation	Aug.82
Emergency brake rebuild	Dec.92
Four wheel disc brakes	Jan.93
Front disc brake updated	Aug.93
Brake lines- for dual exhaust cars	Apr.89
Original master cylinder-rebuild	Mar.82
Original system rebuild	Apr.82
Parking brake assembly diagram	Dec.77
Power booster (late model)-installation	Sep.84
Self adjusting-conversion	Dec.87
Treadle vac. master cylinder-rebuild	Apr.81
Anti-lock ABS brake system installation	Aug.94
That's the brakes	Dec.78
Project "X" car gets disc brakes supplemental section	
Disc brakes	June 75
Dual master cylinder conversion	May 01
Updated disc brakes	June 88

Updated dual master cylinder	July 88
Power brake hint - extra	Oct.94
Bleeding Dual Master Cylinders	May 96
Rear drum brake self-adjusting conv.	May, 98
55-58 big rotor power disk brakes	Dec.01
Disk br. power booster dual M.C.update	June 03
Dual MS conversion w/ GM prop valve	Dec. 03
Conversion	Jun.82/Aug.82
Four wheel	Jan.93
55-58 power disk brake upgrade	March 04
55-58 disk brake update	Feb. 05
55-64 rear disk brake update	July 05
57-64 disk br. w/14" wheels	April 06
Aftermarket booster installation	Oct. 06
5-8 Wilwood disk conversion	April 07
5-7 power brake pedal conversion	April 07

BULBS

Application chart	Dec.77
Finding the right bulb	Feb.94

CARBURETOR

Dual 4 barrel-identification	Apr.86
Four barrel-adjustment	Feb.77
Fuel injection system-exploded view	Oct.76
Oil bath air cleaner element replace	June 01

CLOCK

Electric-removal & cleaning	Mar.78
Digital-installation	Apr.93
Panel-installation	Mar.78

CLUTCH

Hydraulic clutch installation	Oct. 06
-------------------------------	---------

Cooling system

electric radiator fan install	May 07
5-7 radiator shroud dual fan install	July 07

COMPASS

Original-installation	Nov.77
-----------------------	--------

CONTINENTAL KIT

Original-installation	Sep.77
-----------------------	--------

CONVERTIBLE

Automatic top raiser instructions	Jun.77
Special issue	Jun.77
Top frame (exploded view)	Jun.77
Top pump replacement	Jun.77
Top pump, cylinders, hoses-restoration	Aug.86
Top colors	Jun.92
Top frame restoration	Mar.92
55-57 700-R4 install in convertible	Aug. 03

COLOR COMBINATIONS

Exterior paint	Aug.81
Interior paint	Aug.81

COWL TAG

How to identify	Aug.81
Cowl tag ID	Jun.94

DASH AREA

Cruise control installation	Sep..90
Digital dash installation	Apr.93
Instrument cluster (57)-restoration	Jul.86
Instrument cluster (55-56)-restoration	Feb.93
Speedometer repair / restoration	Apr.78
Speedometer (55-56)-restoration	Feb.93
Trim-restoration	Feb.78
Steering wheel-restoration	Sep.86
Padded dash-installation	May 82
55-56 custom instrument cluster install	Oct. 03
55-56 gauge upgrade	Nov. 04
5-6 instrument & clock upgrade	May 06
5-72 speedometer repair	July 07

DOOR

Door hinge rebuild	Mar.90
Door shimming & adjustments	Jul.77
Panel restoration (G.M.)-55	Dec.79
Panel restoration-55 conv.	Mar.80
Weatherstrip installation	Jan.78
57 rear antenna & Door hinge repair	Mar.90
tri-five door assembly	April 02
55-57 Door assembly diagrams	May 03

DRAINS

Front & rear hoses-repair	Apr.83
---------------------------	--------

EXHAUST

Exhaust manifold I.D.	Dec.88
Aluminized Exhaust installation	Feb. 95
Exhaust manifold refinishing	May 81
Turbo muffler, dual exhaust installatin	Oct. 03
5-7 Dual exhaust w/ 2 1/2" rams horn man.	Oct. 04
Dual turbo exh. with cross pipe	Nov. 06

ENGINE

Air cleaner-identification/restoration	Dec.89/Sept.81
Big block-installation	Jun.91/Jul.91/Aug.91
Big block/4 speed installation	Feb.92
Disassemble for restoration	May 86
Fire wall forward detail	Jul.89/Aug.89
Fuel injection facts	Nov.82
Fuel system-troubleshooting	Mar.89
Hardened valve seats-unleaded fuel	May 92
Original-block stampings, all #'s	Aug.81
Original 1956 dual fours-identify	Nov.91/Dec.91
Short block to complete engine-assembly	May 84
Small block side mounts-installation	Mar.91
Spark plug wires-(V-8)-identification	Jan.91
Tune-up	Sept.92
Radiator restoration	Mar.88
Water pump-rebuild	Jan.89
6 cyl. spin on oil filter conversion	July 93
Rear main bearing and seal replacement	Jan.94
Electronic ignition installation	Feb.94
Late model V-8 and auto. trans. installation	Jun.80
Update oil bath air cleaner	Oct.83
55-58 2&4 barrel air filter upgrade	Jan. 05
Upper radiator hose (57- 6 cylinder)	Jan.84
Fan shroud - installation	Jan.84
"Keeping our cool" radiator manufacture	Aug.86
55 power pack engine detailing	July 89
MSD install (multiple spark discharge)	March 95
Big block update!	July 96
Neoprene rear main seal conversion	March 97
Engine starter plate	Sept.97
Remote starter solenoid	Oct.97
Big block installation update	Sept 98
Cruise control installation	Feb. 99
A/c, alt. power steering bracket options	May 01
55-57 tubular core support installation	Aug. 01
55-57 electronic distributor conversion	Sept. 01
serpentine pulley & bracket system install	Jan. 02
V8 to 6cyl. radiator relocation kit install	Feb. 02
Proper starter installation	Aug. 02
Engine starter mounting plate install	Sept. 02
Small block side mount installation	Sept. 03
Cooling that classic Chevy	May 04
55-56 V8 starter plate install	June 04
55-58 4brl. oil bath element upgrade	July 04
55-57 radiator relocation	July 04
55-72 high energy ignition installation	Aug. 04
Neoprene rear main seal conversion	Dec. 04
55-57 cross flow radiator conversion	Jan. 05
55-57 clutch fan conversion	Mar.05
55-57 S.B. side engine mounts	Mar. 05
5-7 header/st. box clearance solution	May 05
5-7 st. linkage/oil pan clearance	June 05
55-72 sm. dia. HEI dist. install	Dec. 05
56-67 V8 oil filter conversion	Jan. 06
5-7 sm. block side mounts install	Jan. 06
5-7 BB vacuum/pressure diagnosis	Feb. 06
55-72 hose clamp sleeve install	Feb. 06
55-72 gear starter & elec. ignition diag.	July 06
5-7 remote master disconnect	July 06

TRI-VALLEY CHEVY CLUB TECH. TIP LIBRARY

DEC. 1974 THRU Dec. 2006

5-7 frontrunner installation	July 06	Front door windows	Feb.75	5-6 custom clock installation	Sept. 05
5-7 elec. cooling fan controller	Sept. 06	Vent window assm. restoration	June 95	55 restore your armrest	Jan. 81
5-7 Big block side mount install	Sept. 06	Hardtop/Convertible Glass Setting	Aug. 95		
5-7 SB LS-1 installation art. 1	March 07	Windshield & Backglass installation	Sept. 95	JACKS	
one piece pan gasket install	May 07	Power window installation 55-57	July 01	Original - identification	Nov.85
5-72 serpentine belt system	June 07	5-7 2dr. HT side glass install	Feb. 04		
		5-7 4dr. side glass & whisker install	Feb. 04	JUDGING	
		55-64 power window conversion	Sept. 04	Sheets - original/modified - explained	Jan.87
FLIPPERS		5-7 vent window latch install	Dec. 05	Clean up for show (car)	Apr.87
Hardtop flipper repair	July 85	5-7 front & rear glass install	Feb. 06	Guidelines / classes	May 86/May 82/July 82
		Sedan whisker strip install art. 4	Feb. 07	Revisions (1987) &(1993)	Jan.87 / Jan.94
		convertible 1/4 window install/adj.	April 07		
FLOOR PAN					
Floor insulation installation	Sept.86	GRAVEL SHIELDS		MIRROR	
Front - installation	Oct.89	Original (1955) - installation	July 82	Original outside - installation	Jul.77
Rear - installation	Sept.89				
Replacement	Aug.78				
FRAMES		GRILLE		MODEL IDENTIFICATION	
Identification	May 91	Exploded views -part numbers	Dec.75	Cowl tag / VIN numbers	Aug.81
VIN's	Feb.91	Horizontal slat (1955) - installation	May 82	VIN's / production dates (55-56)	Dec.88
55-57 cross member replacement	Jan. 01	Tubular grill installation	May 99	VIN's / production dates (57)	Mar.91
		56 Grille installation	June 06	5-7 VIN numbers	April 07
FRONT END		GROMMETS		MOULDING	
A-arm bushing - installation	Jan.88	Location / explanation / CCI part numbers	July 84	Crown moulding (57) retainer - repair	Feb.88
Anti-sway bar - installation (modified)	Jun.85	Grommets, bumpers and plugs	June 96	Stainless part numbers (55)	May 76
Anti-sway bar - installation (original)	Feb.89			Stainless part numbers (56)	Jun.76
Coil spring compressor / how to make	Feb.82	HEADLIGHTS / LIGHTS		Stainless part numbers (57)	Aug.76
Complete rebuild	May 81/ Nov.88	Original headlight identification	July 92	Stainless - proper removal	Oct.85
Dropped spindle installation	Jan.92	Backup light socket (56)	Jan.81	Body sill mouldings	Oct.75
Spindle replacement	July 76	Backup lights for 4-speed setup	Dec.82	Bel-Air beltline stainless removal & install	April 96
2 1/2"lowering coil spring installation	May 97	Test light	Oct.83		
Tubular upper A -arms	July 97	Warning light (radiator support)	Jan.81	NOMAD	
Coil-over shock conversion kit	July 98	Generator light (we've checked everything)	Feb.94	Back glass - installation	Dec.86
2" drop spindles	Aug. 98	55-57 headlight bucket identification	March 01	Headliner - installation	Dec.80
Lower tubular A-arm installation	July 99	L.E.D. tail light conversion 55-57	Nov. 01	Modified shock bar - installation	Aug.77
Suspension rebuild complete pt. 1	Nov. 03	Halogen composite headlight update	Feb. 03	Original seats - restoration	Dec.83
Suspension rebuild complete pt. 2	Dec. 03	55-57 L.E.D. tail lamp upgrade	Aug. 04	Roof pillar - repair	Aug.77
Filler panels for stock core support	Nov. 06	55-57 LED third brake lite install	Feb. 05	Special issue	Aug.77
		55-72 Delta headlight install	Aug. 05	Weatherstrip (lift & tailgate) - installation	Dec.86
		5-7 courtesy light w/ delay module	Aug. 06		
		5-7 lighted vanity mirror install	Aug. 06	PAINT	
FUEL INJECTION				Exterior /interior paint chips	Apr.90
Exploded view	Oct.76	HEADLINER		Original color combinations - exterior	Aug.81
Facts and numbers	Nov.82	Original (Hdtp) - installation	Sept.81	Original combinations - interior	Aug.81
Identification / serial numbers	Jun.86	Original (Nomad) - installation	Dec.80	Show quality finishing	Mar.87
57 Corvette fuel injection R.P.O. 579	June 86			Spring clean-up / color sanding your paint	Mar.93
		HEATER		"What's painted what?"	July 80
		Control levers -repair / replacement	Nov.78	5-7 paint codes	March 07
		Control valve - installation	Nov.83		
FUEL SYSTEM		Restoration (55-56)	Nov.87	PRODUCTION FIGURES / DATES	
Hardened valve seats - unleaded fuel	May 92	Installation (55- 56)	Nov.76	All models (exc. "210" 2dr.Hdtp) paint comb.	Jan.76
Lines - installation for dual exhaust cars	Apr.89	Heater & defrost (57)	Jan.77	"210" 2dr Hdtp	Jun.76
Trouble shooting (gauge & sending unit)	Mar.89	Late model heater installation	Aug.80	VIN's / production dates (1955-1956)	Dec.88
Low fuel warning light module	April 99	New (57) AC/heat system installation	May 89	VIN's / production dates (1957)	Mar.91
55-57 fuel tank & sender identification	Oct 00	55-72 Electronic heat control valve	Feb.05		
56-57 gas filler neck check valve	Jan. 05			RADIO	
55-64 fuel gauge/sender diagnostics	Mar.05			Antenna - see <i>antenna</i> section	
		Horns		Auxiliary speaker "57" - installation	Mar.77
GENERATOR		replacement horn install	June 07	AM/FM cassette stereo - installation	Dec.94
Alt. conversion 57 w/internal reg.	Apr.83			Modified radio installation / solenoid repair	June 89
Alternator conversion / wiring (updated)	Aug.90	INSURANCE		Radio,CD player & panel speakers install	June 99
Original - identification & restoration	Sept.91	Guidelines	Nov.79		
Original rebuild	Dec.81	"What is available?"	Nov.83		
Alternator for 6 cylinder engine	July 83	INTERIOR		REAR END	
55-57 generator to Alt. installation	Feb. 04	Carpet (55-56) -installation	Aug.87	Anti-sway bar (modified) - installation	Jun.85
55-72 one wire self exciting alt. conv.	July 04	Carpet (57) - installation	Feb.91	Differential ratio code - identification	June 84
55-72 charging sys. troubleshooting	Sept. 05	Color combination chart	Mar.76/ Aug. 81	Differential - installation	May 83
		Interior color swatches	Apr.90 / May 94	Late model - conversion	Aug.80/Jun.89
GLASS		Roll-n-pleat inserts	Aug.83	Rear end gear rebuild	Aug.92
Back glass (sedan)-installation	Nov.80	Seat belt (late model) - installation	May 85	Restoration	Mar.86
Back glass (nomad) - installation	Dec.86	Trim combination chart	Mar.76	Rear end lowering kit	Jun.94
Power window installation (after market)	Jul.90	Exterior / interior color combinations	June 78	Pro-look rear chassis conversion	July 94
Power window conversion, door	May78/Apr78	Available seat covers by number	Sept.79	Misc. rear end information	Jan. 97
Sedan side glass installation	Oct.86	Interior installation helpful hints	April 95	Ford 9" conversion	June 98
Sedan quarter window area - restoration	Feb.90	Custom interior install-headliner-part 1	Jan.96	Ford 9" rear end install & spring rest	May 99
Side glass (Hdtp/conv.) - installation	Sept.85	Tweed interior install panels,seats,carpet	Feb.96		
Side glass (wagon) - installation	Feb.82	55-57 inner firewall pad installation	April 04		
Vent window restoration	Sept.82	55-72 carpet installation	April 04		
Wagon side glass installation	Feb. 82	5-7 fr. & rear seat belt install	April 04		
Window channel (sedan) - installation	Sept.83				
Windshield - installation	Aug.83				

TRI-VALLEY CHEVY CLUB TECH. TIP LIBRARY

DEC. 1974 THRU Dec. 2006

RESTORATION

Air vents	Nov.82
Armrests	Jan.81
Body & frame restoration stand	Apr.92
Classic education - a buyer's guide	Jan.90
Convertible top frame restoration	Mar.92
Dash trim	Feb.78
Door panels (1955)	Mar.80
Door/quarter windows-wthrstrp, seals, stops	Apr.85
Exhaust manifolds	Dec.88/May 81
Engine/trans. disassembly for restoration	May 86
Fender (57) assembly	May 87
Fender panel - repair	Apr.80
Fire wall forward detail	Jul.89/Aug 89
Fire wall pad - installation	Aug.84
Flipper (Hdtp) - repair	July 85/Aug.88
Floor pan - installation	Sept.89/Oct.89
Generator	Sept.91
Heater (55-56)	Nov.87
Instrument cluster (57)	July 86
Inner/outer rocker installation	Nov.90
Locating & identifying the correct part	Oct.93
Radiator	Mar.88
Rear end	Mar.86
Sandblasting	Oct.87
Seat spring rebuild	July 89
Seats (Nomad)	Dec.83
Front & rear seat - restoration (55)	Sept.79
Sedan quarter window area restoration	Feb.90
Sheet metal- "where do I start?"	Dec.90
Seat shells - recovered	July 81
Show quality finishing - paint	Mar.87
Stainless steel trim - polishing	Jul.78
Starting a restoration	Mar.85
Sun visor (interior type)	Sept.80
Tail pan installation	Oct.80
Top pump , cylinders , hoses (convertible)	Aug.86
Water pump	Jan.89
Whisker strip (2-Dr. Hdtp.)	Feb.85
Classic chrome plating	Apr.94
How to avoid being taken while restoring	July 81
Let vacuum hose help restore your classic	Oct.80
Restoring wheels	Feb.88

ROCKER MOULDINGS

1955 - Installation	July 82
1957 - installation	Jun.83

SEAT BELTS

Late model - installation	MAY 85
Tri five seat belt installation	Sept. 00
5-7 3 pt retractable seat belt install	March 07

SEDAN DELIVERY

Special issue	Dec.77
---------------	--------

SERIAL NUMBERS

Body / engine	Aug.81
Frame VIN,s	Feb.91

SHOCK MOUNT REPLACEMENT

How to build & install	May 80
Nomad shock bar	Aug.77
Shock relocation	Mar.79
Shorter rear shocks	Feb.88
Modified rear shock crossmember	Oct.94
KYB shock installation	March 99
5-7 rear shock relocation kit	April 05

SILL PLATES

Late model - conversion	Feb.79
-------------------------	--------

STEERING

Power steering control valve - rebuild	Mar.84
Late model "605" with-column shift	Aug.85
Late model PS pump installation	Jan.85
Power steering pump - rebuild	Dec.82
Mast jacket rebuild	Oct.92
Rack & pinion steering conversion	Dec.93
Steering box - rebuild	Mar.83
Steering box - removal	Oct.84

Steering column removal	Oct.84
Steering column - exploded view	Feb.78
Steering wheel - restoration	Sept.86 / Feb.78
Tilt steering column - installation	July 93
Tilt wheel - conversion	July 79
Tilt wheel conversion (sup. to July 79)	Apr.80
Upper steering column - rebuild	July 83
Super G.M. tech.	Aug.79
Grant steering wheel installation	March 95
Ididit steering column installation	May 95
Installing a 605 steering box	Nov. 96
Steering column coupler identification	April 97
Column shift/ flex coupler w/ 605 box	Nov.97
Steering column & coupler applications	April 98
Rack & pinion steering conversion	Oct. 98
Tilt column w/ stock steering wheel	Aug. 00
55-57 steering gearbox rebuild	April 01
5-7 late model PS pump to stock PS	Oct. 04
Control valve - rebuild	Mar.84
Late model (605) column shift	Aug.85
Late model (605) conversion	Feb.79
Pump - late model - installation	Jan.85
Pump - rebuild	Dec.82
Rack & pinion steering conversion	Feb. 97
55-57 P/s pump w/ remote reservoir	Oct 01
late model PS pump to orig. linkage	Nov. 01
Rack & pinion w/tubular crossmember	June02
Rack & pinion update part 2	July 02
55-57 605 power steering update pt. 1	Mar. 03
605 update pt. 2	April 03
5-7 upper steering mast jacket rebuild	April 05
55-58 tilt st. column w/ orig. wheel	May 05
5-7automatic col. conversion for 605	Aug. 05
5-7 670 P/S upgrade	Dec. 05
5-7 st. shaft update 4 rack & pinion	April 06
5-7 R/P steering w/tilt column update	May 06
5-7 P/S pump chrome dress up	June 06
5-7 605/670 with stock column install	June 06
5-7 P/S pump w/remote reservoir	July 06
5-7 Ididit tilt column install update	Aug. 06
Ididit steering column install art.1	Feb. 07
5-7 rack & pinion shaft support art. 2	Feb. 07
5-7 rack & pinion shaft support art. 3	July 07
5-7 steering to header clearance art. 3	Feb. 07

SUN VISORS

Exterior - installation	May 77
Interior - padding / covering directions	Sept.80

SUSPENSION

Coil spring compressor - how to build	Feb.82
Rear leaf - installation	Jun.81
2" drop fr. & rr coil and leaf spring	Sept. 04
5-7 tubular control arm replacement	Nov. 04
55-57 2" drop spindle installation	Dec. 04
5-7 tubular control arms update	May 05
5-7 traction bar installation update	Aug. 05
5-7 comp. ft. suspension rebuild	Sept. 05
5-7 F&R 2" drop& adjustable shocks	Oct. 05
5-7 rear leaf spring pocket kit	March 06
5-7 wagon rear sway bar install	April 06
R. coil over & tapered leaf install	Dec. 06
2" drop spindle installation	Jan. 07
55-57 air ride suspension installation	Feb. 01
5-7 independant suspension	May 07
5-64 coil over shock installation	June 07

TAIL PAN

Installation	Oct. 90
--------------	---------

TRANSMISSION

Disassembly (POWERGLIDE)	May 86
Flex cable linkage for turbo 350 / 400	Oct.80
TH700-4R auto. trans. installation	Jun.93
TH700-4R auto. trans. update	Nov.93
Turbo 350 / small block - installation	Feb.84
Turbo 400 / small block install	Feb.84/Jun.84
Turbo 350 /400 mounts - how to make	May 79
Remanufactured Powerglide	May 88
Clutch return spring - installation	Feb.88
350 turbo installation (updated)	Sept.88
Modified 4 speed std. shift installation	Dec.95

Neutral safety switch	March 95
Modified 4-speed standard shift install	Dec.95
Stop that Powerglide from burping!	Oct. 96
Tri-5 700-R4 install update pt.1	Oct. 92
Tri-5 700-R4 pt. 2	Nov. 02
55-64 700-R4 installation	June 04
5-7 neutral safety switch installation	June 04
55-57 clutch safety switch kit	April 05
Late model trans identification	Dec. 06
Tremec 5 speed installation	Jan. 07

TRUCKS

Cameo article - history	Nov.80
Door - exploded view	Nov.80
Engine stampings / paint codes	Jun.79
Front end -exploded view	Nov.80
Accessory part numbers	Nov.75
I.D. numbers	Feb.76
Identification -1954 or 1955	Sept.85
Grille - exploded view	Jun.79
Part numbers	Sept.79
Special issue	Jun.79 / Apr.91
Transmission I.D. codes	Nov.80
Disc brakes - installation	Apr.91
Trk. engine & serial # identification	Feb. 95
Independant front suspension install	June 98
Independant front suspension part 2	July 98
Cab corner replacement	Aug 98
Wiper system update	Oct. 98
55-66 truck rear axle identification	Aug. 00
55-59 truck options	Sept. 00
55-59 truck front fender identification	Oct. 00
55-59 Door vent assemblies rebuild	Dec. 00
55-59 Door/ vent glass installation	Jan. 01
55-59 Door hinge rebuild	Feb. 01
47-72 hidden tailgate latch	Nov. 04

TRUNK

Sealing trunk area (not weatherstripping)?????	
Weatherstripping - installation	Aug.84
55-57 elec. deck lid release kit	June 05
Electric trunk release	Oct. 06
Trunk lid insulation installation	Dec. 06

VENT WINDOW

Complete restoration (Hdtp /Conv / Nomad)	Sept.82
Vent window assembly restoration	June 95
Vent window deletion all sedans & wagons	Nov.95

WEATHERSTRIPPING

Back glass - installation	Nov.80
Doors - installation	Jan.78
Door / quarter windows	Apr.85
Lift & tailgate (Nomad) - installation	Dec.86
Trunk - installation	Aug.84
Vent window(Hdtp/conv/Nomad)install	Sept.82
Wagon side glass - installation	Feb.82
Whisker strip (2-dr. Hdtp)- restoration	Feb.85
Hdtp / conv. weatherstripping kit information	Mar.94

WINTERIZING

Storage for classics	Nov.81
----------------------	--------

WIPERS

Electric motor - servicing	Jan.78
Updated electric wiper conversion	Sept.93
Vacuum to electric wiper conversion	Nov.92
Wipers "take up the slack"	Feb.81
55-57 elec. wiper motor update	May 01
55-57 elec motor upgrade	May 04
5-7 orig. wiper cable & drum replace	Oct. 05
5-7 updated wiper system	May 06
5-7 windshield washer kit	Sept. 06

TRI-VALLEY CHEVY CLUB TECH. TIP LIBRARY
DEC. 1974 THRU Dec. 2006

WIRING

Cruise control - installation	Sept.90
Directional signal - exploded view	Apr.75
Electrical wiring diagram (1956)	Aug.75
Electrical wiring diagram (1957)	May 75
Fuse panel	Oct.91
Harnesses what's needed 4 each classic	Jan.84
Spark plug (V-8) - identification	Jan.91
Trouble shooting	Oct.91
Which fuse goes where ?	July 93
Body wiring (55)	Mar.75
Updated fuse panel for 1955-1957	Feb.98
Full wiring harness w/ATO fuse block	Dec. 00
55-57 clutch safety switch installation	June 01

Wheels

Measuring a wheel bolt pattern	March 07
--------------------------------	----------

miscellaneous

Wipers, firewall pad, heater & pedal assm.	Feb.87
55 caps, blue flame air cleaner & engine dolly	Feb.89
56 temp. gauge, pw/ brake conver. pot metal	Apr.89
55 firewall forward detail part 2	Aug.89
Classic education: a buyers guide	Jan.90
Road test the 56	Mar.81
For modified eyes only	Oct.81
Conv. right hand drive to left hand drive	Nov.81
Insulate your turbo muffler	Oct.82
License plate spacer	Nov.80
Economy bug screen	Nov.80
Locating & identifying the correct part	Oct.93
Tech Help-Questions & answers II	Oct.95
Wheel & Tire Size	May 96
Cool tags/ Nomad bows & arrows	Jan. 98
Q&A gauge/str.wheel/u joint/glass	Jan.98
Q&A wheel brg./vacuum/belts/vac wiper	Feb.98
Padlock security system installation	Feb. 98
Q&A hood springs, steering, htr. switches	April 98
Q & A no oil to the lifters 265 v-8	Sept. 00
Q&A 55-57 weight of certain vehicles	Sept. 00
Q&A A-arm shaft & block ID	Jan. 01
Q&A misc.	May 01
Q&A 56 sedan delivery B/A & block ID.	Feb. 01
55-64 org. wheel identification	May 06